PIC Aspern A	Airfield	november 1 se junior for principa la disconstructura independentiale del constructivo del c	angagan ya 1888 walka walka walka kana maka 1880 wa 18	MATERIAL PROPERTY CONTRACTOR
		green and all the comment of the transposit and a set a major commentative of the set and the commentative of the commentative	annerssass 155 men mener somhersen menementelle skrivet had av Store på det de 1847 1845 stelles stelle krivet	and the source of the source o
ALUATION	25X1 p	LACE OBTAINED	25X1	·
TE OF CONTENT		25X1		LASINO CAN KILLONG FO :
TE OBTAINED		DATE PREPARED29	September 1953	Charles Sacraffed Marketon Construction
FERENCES	gyaggi kanipu, transis ibi paki gilikirip, sa saka ana dabu dawa sakan aki kanis sakani sakani sakani kanis sa	merkile hann sekile. Transprinterile vaga i kindidang telengalah kehadi palakil USA dibi kili di Sekile sekila	стурная, 1880, 1880, «нясь така», как и назычает метриятель (2000 год компенсация учествувает по выпас и в год -	Allen And God Comment
GES 1	ENCLOSURES (NO. &	TYPE)	haliterations (18 etc.) plantitus reparatuspata arabit tributeites essa territorio, quoden etc. e culture e america	
EMARKS	has management all as considered Affice, 2 of the 42 WAYAN accommendations of	The state of the s		wedgesterlike to team years.
		nghannya Ban Japan 3 miliawa sangkala kanangangaka kata Milanti da Ali Manti-dangka ki jibo yan "katinan masa k	метомин от 15 € 650 № 1481 — Багаранска метомустијан и изакал на гоза за за предвежавата из и колупски година и	CONTRACTOR OF THE P
ra gerinden, der 2 von zugen, gelein gewichte der dem Antonie der Geschaft der der der Geschaft der der der dem				
THE PERSON NAMED IN STREET OF THE PERSON NAMED IN COLUMN TWO PARTY AND THE PERSON NAMED IN COLUMN TWO	, jaganian na uno rengin panalaken merupagai de Alex Panago (A. 1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1	ergens, mer is betrein, se centra (vandada timp in state diseption), engelen begreifenden kan anterioristische		

On 7 September 1953, no change was observed in the status of aircraft and personnel at Aspern (P 49/X 49) airfield. There was no air activity between 10 a.m. and 3 p.m. A take-off strip was marked by small flags. No activity was observed near the Pe-2s. The previous assumption that at least some planes were not capable of flying was confirmed by the observation that the rudder assemblies of four Pe-2s were missing.

25X1

Comment. Aspern airfield is occupied by a fighter regiment.